5

## **ABSTRACT**

A method for detecting wafer flat shift, and an apparatus (500) having two sensors (506a) and (506b) in a power supply circuit (600) for wafer fabrication equipment, the sensors (506a) and (506b) detecting a shift in wafer flat position from a desired position and shutting off the wafer fabrication equipment.

PHI\I123000.3 10